

Village of Teslin

Deep Sand and Gravel Aquifer



Legend

- GROUNDWATER WELLS
- AQUIFER BOUNDARY


0 0.25 0.5 km



Aquifer description (Mapping report 2023)

Confined sand and gravel aquifer located at greater depth in the Village of Teslin area. It is likely the aquifer is more extensive than mapped, but limited information constrains the aquifer's extent. The aquifer is confined by the Teslin Aquitard, a thick layer of glaciolacustrine silt and clay.

| Aquifer details | |
|---|--|
| Municipality | Teslin |
| Water Management Area | Yukon River (https://legislation.yukon.ca/regs/oic2003_058.pdf) |
| No. wells correlated to aquifer | 3 |
| Vulnerability to contamination | Low |
| Productivity | Moderate/High |
| Aquifer classification | 4b |
| Aquifer sub-type | IIIB |
| Hydraulic connectivity | Unlikely |
| Water Licences issued for water wells completed in this aquifer | MN99-025-1 |
| Observation wells (Active, Inactive) | None |



For more information, please contact the Water Resources Branch at water.resources@yukon.ca.

Disclaimer: The data and information provided on this factsheet are provided by the Government of Yukon as a public service. The Government of Yukon does not guarantee the quality, accuracy, completeness or timeliness of any of the information provided. Users should verify all information before acting on it. The Government of Yukon disclaims all warranties, representations, and conditions regarding use of the factsheet, including all implied warranties of merchantability and fitness. The Government of Yukon is not responsible for any direct, indirect, special, incidental, consequential, or any other damages whatsoever, caused, arising out of or in connection with the use of the factsheet, or reliance on the information available on the factsheet, including any other pecuniary loss, whether based on negligence, breach of contract or other cause of action, even if the Government of Yukon has been informed of the possibility thereof. Factsheet generated: 2021-08-30. Detailed methods for all figures are described in Aquifer Mapping Report: Village of Carmacks.

