

	Unit Number	Notes	City	Radon level (Bq/m3)	Recorded Radon level (Bq/m3) post mitigation	Radon vent installed	serial no	date	location									
203 Simpson Dr	8857	Mitigated in May 2019 by All Pro Yukon	Watson Lake	1121	119	Yes	323859-9											
600 College drive lower (one storage room)		Fans installed by Cory Sands Jan 2019	Whitehorse	861		Yes												
Lot 10	8678	Mitigated in September 2018 by E.S. 2 x Elect	Pelly Crossing	761	44	Yes	592537-5											
10 Center Street #1	4110	Mitigated in January 2019 by E.S.	Mayo	575	28	Yes	907360-2											
13 B Ketza Road	0802	Mitigated in August 2018 by E.S. Long term te	Whitehorse	572	30	Yes	218648-4											
1A -2004 Centennial Str	0840	New ground sheet installed. Long term tester i	Whitehorse	524	131	No	905222-6											
25 Laurier Str	8656	partially finished basement	Mayo	491	57	Yes	704185-8											
Lot 90-6/90-7	8790	Mitigated by Cory Sands July 2019	Ross River	426	80	Yes	910649-3	1/4/2022										
Lot 243	8745	Mitigated by Cory Sands July 2019	Ross River	423	44	Yes	327815-7	1/4/2022										
101 Nisutlin	7151	Mitigated in May 2019 by All Pro Yukon	Watson Lake	413	86	Yes	942318-7											
600 College drive lower floor common area		Fans installed by Cory Sands Jan 2019	Whitehorse	373		Yes												
108 Nisutlin	8849	Mitigated in May 2019 by All Pro Yukon	Watson Lake	371		Yes	954161-6											
A-611 Liard	8862	Mitigated in May 2019 by All Pro Yukon	Watson Lake	369	183	Yes	283937-1											
44-13th Avenue	6336	New ground sheet installed. Long term tester i	Whitehorse	336	209	No	135443-0											
106 Nisutlin	8513	Mitigated in May 2019 by All Pro Yukon	Watson Lake	332	27	Yes	605139-5											
125 Campbell	8511	Mitigated in May 2019 by All Pro Yukon	Watson Lake	331	173	Yes	753612-1											
310 5th Ave	8907	Mitigated in May 2019 by All Pro Yukon	Mayo	310	32	Yes	475567-4											
4th St W Lot 179	2621	Mitigated by Cory Sands July 2019	Ross River	299	120	Yes	177660-8	1/4/2022										
205 Simpson Dr	8859	Mitigated in May 2019 by All Pro Yukon	Watson Lake	297	24	Yes	187970-9											
921 Ravenhill	8843	Mitigated in May 2019 by All Pro Yukon	Watson Lake	294	26	Yes	439736-0											
719 Liard	8818	Mitigated in May 2019 by All Pro Yukon	Watson Lake	283	112	Yes	660172-8											
A-716 Liard	1301	Mitigated in May 2019 by All Pro Yukon	Watson Lake	278	34	Yes	950481-2											
1-356 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	second tester 272	46	Yes	971922-0											
106B-2101 Centennial Str	0837	Spray foam done to crawl space	Whitehorse	271	140	No	408198-0											
20 Firth Road	0804	mitigated	Whitehorse	262	73	Yes	484197-9											
149 River Rd	8312	mitigated by Cory Sands Oct 2019	Carmacks	247	45	Yes	282122-1											
105 Nisutlin	8512	Mitigated in May 2019 by All Pro Yukon	Watson Lake	238	55	Yes	984061-2											
4-362 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	233	43	Yes	668899-8											
21B Laurier	1207	Mitigated in May 2019 by All Pro Yukon	Mayo	233	66	Yes	270365-0											
Lot 1001 Quad 115115	8677	Mitigated in May 2019 by All Pro Yukon	Pelly Crossing	230	43	Yes	489943-1											
5-364 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	226	47	Yes	757647-3											
2-358 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	223	41	Yes	217494-4											
1008 Ravenhill Dr	7154	Mitigated in May 2019 by All Pro Yukon	Watson Lake	218	51	Yes	975435-9											
18A Laurier	1205	Mitigated in May 2019 by All Pro Yukon	Mayo	217	30	Yes	279174-7											
101 Rose Cr unit 4	4900	Mitigated by Cory Sands July 2019	Faro	216	28	Yes	542747-1											
311 6th Ave	1201	Mitigated in May 2019 by All Pro Yukon	Mayo	216	29	Yes	984157-8											
37 Hart Crescent	0803	mitigated	Whitehorse	211	19	Yes	653092-7											
1-101 Campbell	8915	Mitigated in May 2019 by All Pro Yukon	Watson Lake	209	61	Yes	596179-2											
131 Alsek	2329	Mitigated in Nov 2019 All Pro Yukon	Haines Junction	204	156	Yes	114936-8											
105 - 408 Alexander Street	3001	finished basment	Whitehorse	204		No	590485-9											
201 Simpson Dr	8855	Mitigated in May 2019 by All Pro Yukon	Watson Lake	203	25	Yes	722453-8											
104A-2101 Centennial Str	0837	Spray Foam done to crawl space	Whitehorse	203	41	No	656946-1											
2B -2004 Centennial Str	0840	mitigated	Whitehorse	203	50	Yes	691549-0											
33 Wann Road	6342	mitigated	Whitehorse	203	108	Yes	444015-2											
C-Wheeler	3004	vent is working -- new fan installed Jan 2019/e	Whitehorse	202	20	Yes	215696-6											
162 Alsek	8445	Mitigated in Nov 2019 All Pro Yukon	Haines Junction	198	61	Yes	683663-9											

Client	Yukon Housing Corp.
Contract manager	Philip Oberg
Report prepared by	AlphaTracker
Competent person	Mahmud Amin
Authorized by	Eric Bjornson
Report status	Complete



Device serial number	Address	City	Province	Device location	Test start	Test end	Test Duration (days)	Radon level (Bq/m3)	General notes	Status
1005453	River Rd 181	Carmacks	Yukon Territory	hallway	2018-11-29	2019-05-01	153	42		Complete
1296177	Simpson Dr 203	Watson Lake	Yukon Territory	basement	2018-11-21	2019-04-25	155	268	mitigation work has	Complete
1625987	Taylor St 508 A	Whitehorse	Yukon Territory	hallway	2018-11-26	2019-04-25	150	29		Complete
1910645	Taylor St 504 C	Whitehorse	Yukon Territory	hallway	2018-11-26	2019-04-25	150	34		Complete
2099232	Taylor St 506 A	Whitehorse	Yukon Territory	hallway	2018-11-26	2019-04-25	150	26		Complete
2365880	Lot 90-6/90-7	Ross River		hallway	2018-11-29	2019-05-01	153	426		Complete
3148897	Nieutlin Dr 120	Watson Lake	Yukon Territory	hallway	2018-11-21	2019-04-25	155	82		Complete
3446812	13th Ave 44	Whitehorse	Yukon Territory	hallway	2019-01-04	2019-04-25	111	346		Complete
3728292	Rowlinson Dr 110	Carmacks	Yukon Territory	hallway	2018-11-29	2019-05-01	153	87		Complete
4110144	Klaza Rd 108 B	Carmacks	Yukon Territory	hallway	2018-11-29	2019-05-01	153	31		Complete
4129417	Jecke I St 506 C	Whitehorse	Yukon Territory	hallway	2018-11-26	2019-04-25	150	31		Complete
4452876	McDade St 112	Carmacks	Yukon Territory	hallway	2018-11-29	2019-05-01	153	129		Complete
4847646	McDade St 110 A	Carmacks	Yukon Territory	hallway	2018-11-29	2019-05-01	153	7		Complete
4979514	Simpson Dr 203	Watson Lake	Yukon Territory	hallway	2018-11-21	2019-04-25	155	223		Complete
7242134	Ketza Rd 13 B	Whitehorse	Yukon Territory	basement	2018-11-30	2019-04-25	146	143		Complete
7312473	Lot 10 A	Pelly Crossing	Yukon Territory	basement	2018-11-15	2019-05-01	167	43		Complete
7787930	Centennial St 2004 1A	Whitehorse	Yukon Territory	hallway	2018-12-05	2019-04-25	141	290		Complete
9912874	St Elias St 113	Haines Junction	Yukon Territory	hallway	2018-12-10	2019-04-26	137	69		Complete

Device serial number	Social/Senior/Staff	Address	City	Device location	Test start	Test end	Test Duration (d)	Radon level (Bq/m3)	General notes	level (Bq/m3) post m	2019 notes
2429249		Detector added to collected detect	410 Jarvis	In with all collected detectors	2017-11-30	2018-03-12	102	5	shipment of all detectors		
2037901		410 Jarvis General CDM area	410 Jarvis Head office	General CDM area	2017-11-30	2018-03-07	97	30			
7311624		410 Jarvis General Housing Ope	410 Jarvis Head office	General Housing Operations area	2017-11-30	2018-03-07	97	32			
7567407		410 Jarvis Office 100	410 Jarvis Head office	Darrens Office	2017-11-30	2018-03-07	97	40			
5843313		410 Jarvis Office 101	410 Jarvis Head office	Lesters office	2017-11-30	2018-03-07	97	59			
3727559		410 Jarvis Office 104	410 Jarvis Head office	Manager Building Maintenance	2017-11-30	2018-03-07	97	16			
1815273		410 Jarvis Office 115	410 Jarvis Head office	Nigels office	2017-11-30	2018-03-07	97	31			
4611687		410 Jarvis Office 116	410 Jarvis Head office	Megans office	2017-11-30	2018-03-07	97	32			
2669430		410 Jarvis Office 117	410 Jarvis Head office	Evas office	2017-11-30	2018-03-07	97	30			
6444472		410 Jarvis Office 118	410 Jarvis Head office	Leahs office	2017-11-30	2018-03-07	97	33			
6940589		410 Jarvis Office 119	410 Jarvis Head office	Kim Corothers office	2017-11-30	2018-03-07	97	20			
4173100		410 Jarvis Office 120	410 Jarvis Head office	Kim Sharps Office	2017-11-30	2018-03-07	97	20			
3175163		Detector added to collected detect	410 Jarvis Head office	In with all collected detectors	2017-11-30	2018-03-12	102	17	collect detector		
7630692		Detector added to collected detect	410 Jarvis Head office	In with all collected detectors	2017-11-30	2018-03-12	102	12	shipment of all detectors		
1606516		Detector added to collected detect	410 Jarvis Head office	In with all collected detectors	2017-11-30	2018-03-12	102	7	shipment of all detectors		
7193378		Detector added to collected detect	410 Jarvis Head office	In with all collected detectors	2017-11-30	2018-03-12	102	7	shipment of all detectors		
2265957		Detector added to collected detect	410 Jarvis Head office	In with all collected detectors	2017-11-30	2018-03-12	102	0	shipment of all detectors		
3584406	Staff	Lot 1, Bk 8	Beaver Creek	Hallway	2017-11-21	2018-03-03	102	57			
2239986	Staff	Lot 1, Bk 8 second tester	Beaver Creek	Hallway	2017-11-21	2018-03-03	102	64	Second radon tester		
4884763	Staff	Lot 2, Bk 8	Beaver Creek	Hallway	2017-11-21	2018-03-03	102	81			
1682582	Staff	Lot 21, Bk 9	Beaver Creek	Hallway	2017-11-21	2018-03-03	102	181			
7954308	Social	Simmons Ave 408 Lot 41	Carcross	Hallway	2017-12-01	2018-03-06	95	54			
9711334	Staff	Simmons Ave 412 Lot 43	Carcross	Hallway	2017-12-01	2018-03-06	95	99			
2032944	Social	Simmons Ave 415 Lot 30	Carcross	Hallway	2017-12-01	2018-03-06	95	39			
7144454	Social	Tagish Ave 209 Lot 5 Block 19	Carcross	On Stairs	2017-12-01	2018-03-06	95	97			
2264745	Social	Tagish Ave 211 Lot 6 Block 19	Carcross	Main Room	2017-12-01	2018-03-06	95	71			
5641998	Staff	Tagish Ave 306 Lot 10, Block 3	Carcross	Kitchen	2017-12-01	2018-03-06	95	39			
2572642	Social	Tagish Ave. 205 Lot 3 Bk 19	Carcross	On Stairs	2017-12-01	2018-03-06	95	116			
4298972	Social	Tagish Ave. 207 Lot 4 Bk 19	Carcross	Main Room	2017-12-01	2018-03-06	95	26			
1787720	Staff	Tutshi Ave 208 Lot 9, Block 19	Carcross	Kitchen	2017-12-01	2018-03-06	95	56			
9878687	Staff	Tutshi Ave 210 Lot 8, Block 19	Carcross	Kitchen	2017-12-01	2018-03-06	95	64			
2662385	Social	Klaaza 108A	Carmacks	Hallway	2017-11-24	2018-03-06	102	19			
7662675	Social	Klaaza 108B	Carmacks	Hallway	2017-11-24	2018-03-06	102			411014-4--11/29/2018--Rob--Hallway	
4254843	Staff	Klaaza 111	Carmacks	Hallway	2017-11-24	2018-03-06	102	93			
6145585	Staff	Klaaza 111 second radon tester	Carmacks	Hallway	2017-11-24	2018-03-06	102	87	Second radon tester		
4651402	Social	McDade 104	Carmacks	Hallway	2017-11-24	2018-03-06	102	74			
4164794	Social	McDade 108	Carmacks	Hallway	2017-11-24	2018-03-06	102	166			
3432539	Social	McDade 110A	Carmacks	Hallway	2017-11-24	2018-03-06	102			484764-6--11/29/2018--Rob--Hallway	
3464759	Social	McDade 110B	Carmacks	Hallway	2017-11-24	2018-03-06	102	49			
2151058	Social	McDade 111	Carmacks	Hallway Base	2017-11-24	2018-03-06	102	44			
4293310	Social	McDade 112	Carmacks	Hallway	2017-11-24	2018-03-06	102			445287-6--11/29/2018--Rob--Hallway	
3908654	Social	McDade St 107A	Carmacks	Hallway	2017-11-24	2018-03-06	102	38			
3702362	Social	McDade St 107B	Carmacks	Hallway	2017-11-24	2018-03-06	102	54			
2003127	Social	McDade St 107C	Carmacks	Hallway	2017-11-24	2018-03-06	102	62			
1620442	Social	McDade St 107D	Carmacks	Hallway	2017-11-24	2018-03-06	102	62			
1079037	Social	McDade St 107D second radon t	Carmacks	Hallway	2017-11-24	2018-03-06	102	59	Second radon tester		
3578176	Social	Prospector 104	Carmacks	Hallway	2017-11-24	2018-03-06	102	34			
4098083	Social	Prospector 108	Carmacks	Hallway	2017-11-24	2018-03-06	102	62			
5052014	Social	Prospector 110	Carmacks	Hallway	2017-11-24	2018-03-06	102	115			
2129054	Social	Prospector 110 second tester	Carmacks	Hallway	2017-11-24	2018-03-06	102	114	Second radon tester		
2177988	Social	Prospector 112	Carmacks	Hallway	2017-11-24	2018-03-06	102	82			
1486000	Staff	River Rd 125A	Carmacks	Hallway	2017-11-24	2018-03-06	102	49			
9939406	Staff	River Rd 125B	Carmacks	Hallway	2017-11-24	2018-03-06	102	88			
3618857	Staff	River Rd 149	Carmacks	Hallway	2017-11-24	2018-03-06	102	247			
2127926	Staff	River Rd 167	Carmacks	Hallway	2017-11-24	2018-03-06	102	67			
4181244	Staff	River Rd 181	Carmacks	Hallway	2017-11-24	N/A	102	N/A	Reported by YHC as not sent		100545-3--11/29/2018--Rob--Hallway
7039969	Staff	Rowlinson Dr 102	Carmacks	Hallway	2017-11-24	2018-03-06	102	69			
2426948	Social	Rowlinson Dr 103	Carmacks	Hallway	2017-11-24	2018-03-06	102	50			
5543400	Social	Rowlinson Dr 104	Carmacks	Hallway	2017-11-24	2018-03-06	102	67			
2427144	Staff	Rowlinson Dr 106	Carmacks	Bsmt Hallway	2017-11-24	2018-03-06	102	137			
1017417	Staff	Rowlinson Dr 107	Carmacks	Hallway	2017-11-24	2018-03-06	102	67			
7424195	Staff	Rowlinson Dr 109A	Carmacks	Hallway	2017-11-24	2018-03-06	102	67			
4971149	Staff	Rowlinson Dr 109B	Carmacks	Hallway	2017-11-24	2018-03-06	102	45			
2148737	Staff	Rowlinson Dr 110	Carmacks	Hallway	2017-11-24	2018-03-06	102			372829-2--11/29/2018--Rob--Hallway	
1243286	Staff	Rowlinson Dr 112	Carmacks	Bsmt Hallway	2017-11-24	2018-03-06	102	60			
3449527	Staff	Tanilus Dr 102	Carmacks	Hallway	2017-11-24	2018-03-06	102	59			
4290227	Social	Victoria Cr 104A	Carmacks	Hallway	2017-11-24	2018-03-06	102	24			
7725773	Social	Victoria Cr 104B	Carmacks	Hallway	2017-11-24	2018-03-06	102	45			
6432595	Social	Victoria Cr 108	Carmacks	Hallway	2017-11-24	2018-03-06	102	46			
4172938	Staff	Victoria Cr. 106A	Carmacks	Living Room	2017-11-24	2018-03-06	102	28			
4297842	Staff	Victoria Cr. 106B	Carmacks	Hallway	2017-11-24	2018-03-06	102	56			
9764028	Social	Victoria Cr. 106B second tester	Carmacks	Hallway	2017-11-24	2018-03-06	102	41	Second radon tester		
7935893	Social	2nd Ave 1238	Dawson	Hallway	2017-11-09	2018-02-28	111	43			
6857445	Staff	4th Ave 749	Dawson	Hallway	2017-11-09	2018-02-28	111	41			
4293775	Staff	4th Ave 847	Dawson	Hallway	2017-11-09	2018-02-28	111	26			
7530975	Staff	4th Ave 851 second tester	Dawson	Bedroom Hallway	2017-11-09	2018-02-28	111	53	Second radon tester		
3141900	Staff	4th Ave 863	Dawson	Hallway	2017-11-09	2018-02-28	111	44			
4303608	Staff	4th Ave 867	Dawson	Hallway	2017-11-09	2018-02-28	111	26			
3328234	Staff	4th Ave 897	Dawson	Hallway	2017-11-09	2018-02-28	111	41			
7198344	Staff	5th Ave 1376	Dawson	Living Rm/Hallway	2017-11-09	2018-02-28	111	55			
9419706	Social	5th Ave 982	Dawson	Hallway	2017-11-08	2018-02-28	112	45			
7569809	Staff	5th Ave 994	Dawson	Hallway	2017-11-08	2018-02-28	112	49			
1214931	Staff	6th Ave 602	Dawson	Hallway	2017-11-08	2018-02-28	112	47			

7352768	Staff	6th Ave 854	Dawson	Hallway	2017-11-09	2018-02-28	111	76			
4226379	Staff	6th Ave 867	Dawson	Hallway	2017-11-09	2018-02-28	111				
2169845	Staff	6th Ave 876	Dawson	Hallway	2017-11-09	2018-02-28	111	73			
6850291	Staff	6th Ave 941	Dawson	Hallway	2017-11-08	2018-02-28	112	42			
4296364	Staff	6th Ave 941 second tester	Dawson	Hallway	2017-11-08	2018-02-28	112	39	Second radon tester		
4295267	Staff	6th Ave 957	Dawson	Hallway	2017-11-08	2018-02-28	112	42			
3323375	Staff	6th Ave 967	Dawson	Hallway	2017-11-08	2018-02-28	112	44			
2580215	Staff	6th Ave 975	Dawson	Hallway	2017-11-08	2018-02-28	112	36			
7945538	Staff	6th Ave 976	Dawson	Hallway	2017-11-09	2018-02-28	111	51			
1358258	Staff	6th Ave 983	Dawson	Hallway	2017-11-08	2018-02-28	112	56			
1550060	Staff	6th Ave 991	Dawson	Hallway	2017-11-08	2018-02-28	112	44			
1237882	Staff	7th Ave 701	Dawson	Living Room	2017-11-08	2018-02-28	112	90			
3265923	Senior	7th Ave 846-1	Dawson	Hallway	2017-11-08	2018-02-28	112	40			
3559044	Senior	7th Ave 846-1 second tester	Dawson	Hallway	2017-11-08	2018-02-28	112	56	Second radon tester		
4204053	Senior	7th Ave 846-2	Dawson	Hallway	2017-11-08	2018-02-28	112	32			
3628658	Senior	7th Ave 846-3	Dawson	Hallway	2017-11-08	2018-02-28	112	51			
2023232	Senior	7th Ave 846-4	Dawson	Hallway	2017-11-08	2018-02-28	112	50			
4296794	Social	7th Ave 933	Dawson	Hallway	2017-11-08	2018-02-28	112	23			
2033884	Social	7th Ave 941	Dawson	Hallway	2017-11-08	2018-02-28	112	58			
6878417	Social	7th Ave 957	Dawson	Hallway	2017-11-08	2018-02-28	112	50			
1342419	Social	7th Ave 967	Dawson	Hallway	2017-11-08	2018-02-28	112	72			
2571438	Social	7th Ave 975	Dawson	Hallway	2017-11-08	2018-02-28	112	57			
2677326	Staff	Craig St 431	Dawson	Living Room	2017-11-08	2018-02-28	112	102			
1588763	Staff	Craig St 433	Dawson	Living Room	2017-11-08	2018-02-28	112	76			
7437221	Staff	Craig St 453	Dawson	Living Room	2017-11-08	2018-02-28	112	133			
9814948	Staff	Craig St 455	Dawson	Living Room	2017-11-08	2018-02-28	112	157			
3731403	Social	Craig St 455 second tester	Dawson	Living Room	2017-11-08	2018-02-28	112	158	Second radon tester		
4230454	Social	Dugas St 311	Dawson	Bottom of stairwell	2017-11-08	2018-02-28	112	54			
2268407	Social	Dugas St 313	Dawson	Hallway	2017-11-08	2018-02-28	112	63			
7265630	Social	Dugas St 325	Dawson	Base of stairs	2017-11-08	2018-02-28	112	86			
3973505	Social	Dugas St 325 second tester	Dawson	Base of stairs	2017-11-08	2018-02-28	112	106	Second radon tester		
4301617	Staff	Dugas St 337	Dawson	Living Room	2017-11-08	2018-02-28	112	88			
7800562	Staff	Dugas St 526	Dawson	Living Room	2017-11-08	2018-02-28	112	76			
1714781	Staff	Firth St 502	Dawson	Base of stairs	2017-11-08	2018-02-28	112	47			
1091206	Social	Firth St 516	Dawson	Base of stairs	2017-11-08	2018-02-28	112	47			
2577088	Social	Firth St 526	Dawson	Base of stairs	2017-11-08	2018-02-28	112	51			
9731522	Social	Firth St 534	Dawson	Base of stairs	2017-11-08	2018-02-28	112	56			
4278354	Social	Firth St 542A	Dawson	Base of stairs	2017-11-08	2018-02-28	112	46			
1213867	Social	Firth St 542B	Dawson	Base of stairs	2017-11-08	2018-02-28	112	41			
7657620	Social	Grant St 501	Dawson	Base of stairs	2017-11-08	2018-02-28	112	50			
4304705	Staff	Grant St 502A	Dawson	Living Room/Hall	2017-11-08	2018-02-28	112	11	<15 Bq/m3		
4292942	Staff	Grant St 502B	Dawson	Hall Between Bd Rm	2017-11-08	2018-02-28	112	44			
7238215	Social	Grant St 513	Dawson	Base of stairs	2017-11-08	2018-02-28	112	46			
2065647	Social	Grant St 537	Dawson	Base of stairs	2017-11-08	2018-02-28	112	44			
4306890	Social	Grant St 547	Dawson	Base of stairs	2017-11-08	2018-02-28	112	53			
1994979	Senior	Kinsey Manor 101	Dawson	Hallway by Bedroom	2017-11-07	2018-02-28	113	32			
3287604	Senior	Kinsey Manor 101 second tester	Dawson	Hallway by Bedroom	2017-11-07	2018-02-28	113	36	Second radon tester		
4305561	Senior	Kinsey Manor 102	Dawson	Hallway by Bedroom	2017-11-07	2018-02-28	113	41			
7935141	Senior	Kinsey Manor 103	Dawson	by bedroom door	2017-11-07	2018-02-28	113	40			
1627504	Senior	Kinsey Manor 104	Dawson	Hallway by Bedroom	2017-11-07	2018-02-28	113	37			
1742352	Senior	Kinsey Manor 105	Dawson	Hallway by Bedroom	2017-11-07	2018-02-28	113	41			
2569093	Senior	Kinsey Manor 106	Dawson	by bedroom door	2017-11-07	2018-02-28	113	42			
1236249	Social	Turner St 306	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	70			
4303798	Social	Turner St 316	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	90			
2192607	Social	Turner St 324A	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	59			
5374707	Social	Turner St 324A second tester	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	47	Second radon tester		
5589254	Social	Turner St 324B	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	68			
7647050	Social	Turner St 346A	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	79			
9997131	Social	Turner St 346B	Dawson	Bottom of stairwell	2017-11-07	2018-02-28	113	154			
6279285	Social	Turner St 351-101 second tester	Dawson	Bedroom Doorway	2017-11-07	2018-02-28	113	59	Second radon tester		
2379279	Staff	Turner St 372 second tester	Dawson	Main Room (Bach Pad)	2017-11-07	2018-02-28	113	157	Second radon tester		
3400793	Staff	Turner St 372-1	Dawson	Main Room (Bach Pad)	2017-11-07	2018-02-28	113	155			
3293123	Staff	Turner St 372-2	Dawson	Hall Between Bd Rm	2017-11-07	2018-02-28	113	83			
2573277	Staff	Turner St 372-3	Dawson	Hallway/Bedroom	2017-11-07	2018-02-28	113	61			
9931825	Social	Turner Street 351-101	Dawson	Bedroom Doorway	2017-11-07	2018-02-28	113	62			
9996760	Social	Turner Street 351-102	Dawson	Bedroom Doorway	2017-11-07	2018-02-28	113	66			
7514029	Social	Turner Street 351-103	Dawson	Bedroom Doorway	2017-11-07	2018-02-28	113	41			
3432523	Social	Turner Street 351-104	Dawson	Living/Bed wall	2017-11-07	2018-02-28	113	66			
1437029	Staff	Turner Street 351-105-office	Dawson	Wendy's Office	2017-11-07	2018-02-28	113	41			
3651122	Social	Turner Street 351-106	Dawson	Bed/Living Wall	2017-11-07	2018-02-28	113	43			
5190863	Social	Turner Street 351-107	Dawson	Bed/Living Wall	2017-11-07	2018-02-28	113	37			
6427512	Social	Turner Street 351-108	Dawson	Bed/Living Wall	2017-11-07	2018-02-28	113	56			
2272920	Social	Turner Street 351-109	Dawson	Bed/Living Wall	2017-11-07	2018-02-28	113	35			
4290037	Social	Turner Street 351-110	Dawson	Bed/Living Wall	2017-11-07	2018-02-28	113	55			
3546827	Staff	Lot 15, Group 852	Destruction Bay	Hallway	2017-11-21	2018-03-05	104	15			
1625680	Staff	Lot 16 Group 852	Destruction Bay	Hallway	2017-11-21	2018-03-05	104	135			
6626253	Staff	Campbell St 356-1	Faro	Base of stairs (Main Floor)	2017-11-16	2018-03-02	106	267			
7441033	Staff	Campbell St 356-1 second tester	Faro	Base of stairs (Main Floor)	2017-11-16	2018-03-02	106	272	Second radon tester		
4261889	Staff	Campbell St 358-2	Faro	Base of stairs (Main Floor)	2017-11-16	2018-03-02	106	223			
5925755	Staff	Campbell St 360-3	Faro	Base of stairs (Main Floor)	2017-11-16	2018-03-02	106	183			
2533438	Staff	Campbell St 362-4	Faro	Base of stairs (Main Floor)	2017-11-16	2018-03-02	106	233			
6887582	Staff	Campbell St 364-5	Faro	Base of stairs (Main Floor)	2017-11-16	2018-03-02	106	226			
3606951	Social	Dawson Dr 210	Faro	Hallway	2017-11-16	2018-03-02	106	92			
4304440	Social	Dawson Dr 222	Faro	Hallway	2017-11-16	2018-03-02	106	64			
3407566	Staff	Dawson Dr 228	Faro	Hallway	2017-11-16	2018-03-02	106	34			
4127221	Social	Dawson Dr 372	Faro	Hallway	2017-11-16	2018-03-02	106	59			
3745494	Social	Dawson Dr 382	Faro	Hallway	2017-11-16	2018-03-02	106	58			
9688961	Staff	Douglas Dr 510	Faro	Bedroom Hallway	2017-11-16	2018-03-02	106	102			
2558385	Social	Douglas Dr 510 second tester	Faro	Bedroom Hallway	2017-11-16	2018-03-02	106	107	Second radon tester		
4361572	Staff	Douglas Dr 521	Faro	Basement Hallway	2017-11-16	2018-03-02	106	55			
1163807	Staff	Douglas Dr 527	Faro	Basement Hallway	2017-11-16	2018-03-02	106	52			

d probably be 3475365	Staff	Lapie 4	Faro	Hallway	2017-11-16	2018-03-02	106	55			
3640489	Senior	Rose Cr 101	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	216			
1296839	Senior	Rose Cr 101	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	104			
5775697	Senior	Rose Cr 101	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	99			
2076586	Senior	Rose Cr 101	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	96			
2216539	Senior	Rose Cr 101	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	86			
4452680	Senior	Rose Cr 101	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	67			
2032423	Senior	Rose Cr 101 second tester	Faro	Living Room/Bedroom	2017-11-16	2018-03-02	106	101	Second radon tester		
3072535	Staff	Aisek 106	Haines Junction	Hallway	2017-11-22	2018-03-06	104	109			
4306544	Social	Aisek 114	Haines Junction	Hallway Basement	2017-11-22	2018-03-02	100	62			
2550051	Social	Aisek 131	Haines Junction	Hallway Basement	2017-11-22	2018-03-06	104	204			
2429769	Staff	Aisek 141	Haines Junction	Hallway	2017-11-22	2018-03-02	100	151			
1218346	Staff	Aisek 149	Haines Junction	Hallway	2017-11-22	2018-03-06	104	82			
9854928	Social	Aisek 151	Haines Junction	Hallway	2017-11-22	2018-03-02	100	151			
4292256	Staff	Aisek 162	Haines Junction	Hallway	2017-11-22	2018-03-02	100	198			
4305439	Staff	Aisek 164	Haines Junction	Hallway	2017-11-22	2018-03-06	104	100			
4300471	Social	Auriol 102	Haines Junction	Hallway	2017-11-22	2018-03-02	100	67			
4220737	Social	Auriol 104	Haines Junction	Hallway	2017-11-22	2018-03-02	100	135			
4293049	Staff	Auriol 106	Haines Junction	Hallway	2017-11-22	2018-03-06	104	93			
4300687	Social	Dezadeesh 107	Haines Junction	Hallway	2017-11-22	2018-03-06	104	54			
3965431	Staff	Dezadeesh 107 second tester	Haines Junction	Hallway	2017-11-22	2018-03-06	104	44	Second radon tester		
4377321	Senior	Martin St 141-1	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	30			
4300331	Senior	Martin St 141-2	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	30			
7138308	Senior	Martin St 141-3	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	50			
1207851	Senior	Martin St 141-4	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	31			
6800536	Senior	Martin St 141-5	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	26			
7846900	Senior	Martin St 141-5	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	15			
6122956	Senior	Martin St 141-6	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	30			
9931676	Senior	Martin St 141-7	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	49			
3975638	Senior	Martin St 141-8	Haines Junction	Bedroom	2017-11-22	2018-03-06	104	28			
4167631	Senior	Martin St 141-9	Haines Junction	Bedroom	2017-11-22	2018-03-02	100	45			
1708644	Social	Rainbow 105	Haines Junction	Hallway Basement	2017-11-22	2018-03-02	100	117			
1687524	Social	Rainbow 108	Haines Junction	Hallway Basement	2017-11-22	2018-03-02	100	134			
9737768	Social	Rainbow 111	Haines Junction	Hallway Basement	2017-11-22	2018-03-02	100	96			
4360558	Social	St. Elias 105	Haines Junction	Hallway	2017-11-22	2018-03-06	104	155			
4218053	Social	St. Elias 107	Haines Junction	Hallway	2017-11-22	2018-03-06	104	97			
4304564	Social	St. Elias 107 second tester	Haines Junction	Hallway	2017-11-22	2018-03-06	104	47	Second radon tester		
3265535	Social	St. Elias 111	Haines Junction	Hallway	2017-11-22	2018-03-06	104	87			
2385995	Social	St. Elias 113	Haines Junction	Hallway	2017-11-22	2018-03-02	100				991287-4--12/10/2018--Phil--Hallway
4108692	Social	1st Ave 104	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	80			
6475859	Staff	1st Ave 106	Mayo	Living Room	2017-11-17	2018-03-05	108	118			
2190197	Staff	1st Ave 112	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	146			
1512383	Staff	1st Ave 401	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	82			
7021041	Staff	2nd Ave 101	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	74			
5854237	Staff	2nd Ave 103	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	92			
4306098	Social	2nd Ave 103 second tester	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	75	Second radon tester		
3552320	Staff	2nd Ave 111	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	90			
3351640	Staff	2nd Ave 112	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	103			
4938502	Staff	2nd Ave 113	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	168			
7483878	Staff	2nd Ave 115	Mayo	Basement Hallway	2017-11-17	2018-03-05	108	105			
1663954	Social	3rd Ave 315	Mayo	Hallway	2017-11-17	2018-03-05	108	122			
6125132	Social	4th Ave 307	Mayo	Hallway	2017-11-17	2018-03-05	108	75			
2370443	Staff	5th Ave 310	Mayo	Main Floor Hallway	2017-11-17	2018-03-05	108	310			
5714209	Staff	5th Ave 402A	Mayo	Base of stairs	2017-11-17	2018-03-05	108	113			
7627268	Staff	5th Ave 402B	Mayo	Base of stairs	2017-11-17	2018-03-05	108	170			
4111928	Social	6th Ave 311	Mayo	Base of stairs	2017-11-17	2018-03-05	108	216			
1886796	Social	6th Ave 313	Mayo	Base of stairs	2017-11-17	2018-03-05	108	82			
5519525	Senior	Center St 10-1	Mayo	Main Living	2017-11-17	2018-03-05	108	576			
2376358	Senior	Center St 10-2	Mayo	Main Living	2017-11-17	2018-03-05	108	109			
1703339	Senior	Center St 10-2 second tester	Mayo	Main Living	2017-11-17	2018-03-05	108	73	Second radon tester		
2006203	Senior	Center St 10-3	Mayo	Main Living	2017-11-17	2018-03-05	108	104			
7725211	Senior	Center St 10-4	Mayo	Main Living	2017-11-17	2018-03-05	108	123			
9897844	Senior	Center St 10-5	Mayo	Main Living	2017-11-17	2018-03-05	108	72			
1748169	Senior	Center St 10-6	Mayo	Main Living	2017-11-17	2018-03-05	108	117			
6901813	Staff	Laurier 18A	Mayo	Base of stairs	2017-11-17	2018-03-05	108	217			
3729167	Staff	Laurier 18B	Mayo	Base of stairs	2017-11-17	2018-03-05	108	111			
9831744	Social	Laurier 20A	Mayo	Living Room	2017-11-17	2018-03-05	108	84			
1676295	Social	Laurier 20A second tester	Mayo	Living Room	2017-11-17	2018-03-05	108	82	Second radon tester		
3126703	Social	Laurier 20B	Mayo	Living Room	2017-11-17	2018-03-05	108	122			
9965630	Social	Laurier 21A	Mayo	Base of stairs	2017-11-17	2018-03-05	108	93			
4300513	Social	Laurier 21B	Mayo	Base of stairs	2017-11-17	2018-03-05	108	235			
2351898	Staff	Laurier 25	Mayo	Basement	2017-11-17	2018-03-05	108	491			
4301461	Staff	896, 897 Old Crow	Old Crow	Living Room	2017-12-02	2018-03-05	93	12	<15 Bq/m3		
6560197	Staff	896, 897 Old Crow	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	5	<15 Bq/m3		
3380441	Staff	896, 897 Old Crow	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	4	<15 Bq/m3		
4299038	Staff	896, 897 Old Crow	Old Crow	Living Room	2017-12-02	2018-03-05	93	0	<15 Bq/m3		
4299160	Staff	896, 897 Old Crow second tester	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	23	Second radon tester		
1584101	Staff	898, 899 Old Crow	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	15			
2564607	Staff	898, 899 Old Crow	Old Crow	Living Room	2017-12-02	2018-03-05	93	14	<15 Bq/m3		
7181373	Staff	898, 899 Old Crow	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	12	<15 Bq/m3		
4302329	Staff	898, 899 Old Crow	Old Crow	Living Room	2017-12-02	2018-03-05	93	0	<15 Bq/m3		
4744116	Staff	Conservation Officer Unit	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	22			
4823191	Staff	Lot 1024	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	10	<15 Bq/m3		
2328847	Staff	Lot 1024	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	9	<15 Bq/m3		
2881654	Staff	Lot 1024 second tester	Old Crow	Master bedroom	2017-12-02	2018-03-05	93	13	Second radon tester		
1127257	Staff	Lot 10	Pelly Crossing	upstairs linen closet	2017-12-02	2018-02-27	87	761	mitigated by Erik S in Sept 2018. Sealed obvious spots	4	Device 731247-3(bsmr stair wall) & 986354-9(Top of stairs) 11/15/2018--Brand--Electronic device still in bsmt
3473808	Staff	Lot 10	Pelly Crossing	upstairs linen closet	2017-12-02	2018-02-27	87	51			
2395788	Staff	Lot 1001 Quad 115115	Pelly Crossing	Hallway	2017-12-02	2018-02-27	87	230			
7517659	Staff	Lot 12 Group 953	Pelly Crossing	Hallway	12/2/2017	2/27/2018	87	74			

5892245	Staff	Lot 12 Group 953	Pelly Crossing	Linen Closet	2017-12-02	2018-02-27	87	69			
7981046	Staff	Lot 12 Group 953	Pelly Crossing	Linen Closet	2017-12-02	2018-02-27	87	67			
5448765	Staff	Lot 12 Group 953	Pelly Crossing	Hallway	2017-12-02	2018-02-27	87				
9833799	Staff	Lot 12 Group 953 second tester	Pelly Crossing	Hallway	2017-12-02	2018-02-27	87	103	Second radon tester		
4296737	Staff	Lot 16 Group 953	Pelly Crossing	Hallway	2017-12-02	2018-02-27	87	168			
3473531	Staff	Lot 22 Group 953	Pelly Crossing	Master bedroom	2017-12-02	2018-02-27	87	105			
7734445	Staff	Lot 26 Group 953	Pelly Crossing	Hallway	2017-12-02	2018-02-27	87	118			
3873225	Staff	1st Ave & 2nd St second tester	Ross River	Hallway	2017-11-15	2018-03-02	107	170	Second radon tester		
6924625	Staff	1st Ave & 2nd St. Apt A	Ross River	Hallway	2017-11-15	2018-03-02	107	169			
6675003	Staff	1st Ave & 2nd St. Apt B	Ross River	Hallway	2017-11-15	2018-03-02	107	82			
7156011	Staff	1st Ave & 2nd St. Apt C	Ross River	Hallway	2017-11-15	2018-03-02	107	77			
4018800	Social	3rd St W Lot 49	Ross River	Hallway	2017-11-15	2018-03-02	107	27			
3286630	Social	3rd St W Lot 57	Ross River	Hallway	2017-11-15	2018-03-02	107	46			
2163749	Social	3rd St W Lot 60	Ross River	Hallway	2017-11-15	2018-03-02	107	91			
2269439	Social	3rd St W Lot 64	Ross River	Hallway	2017-11-15	2018-03-02	107	103			
3353166	Social	4th St W	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	187			
2606069	Social	4th St W Lot 179	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	299			
7896855	Social	5th St W	Ross River	Hallway	2017-11-15	2018-03-02	107	68			
2822211	Social	5th St W Lot 189	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	131			
6907703	Social	5th St W Lot 191	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	159			
2557684	Social	5th St W Lot 194	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	113			
7445828	Social	5th St W Lot 207	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	72			
1023266	Social	5th St W Lot 210	Ross River	Basement Bedroom	2017-11-15	2018-03-02	107	115			
2212975	Social	Barite	Ross River	Hallway	2017-11-15	2018-03-02	107	35			
3117488	Social	Barite St 1	Ross River	Hallway	2017-11-15	2018-03-02	107	34			
2528206	Social	Barite St 3	Ross River	Hallway	2017-11-15	2018-03-02	107	35			
4070595	Social	Barite St 4A	Ross River	Hallway	2017-11-15	N/A	0	N/A	Reported by YHC as not sent		
9678640	Social	Barite St 4A	Ross River	Hallway	2017-11-15	2018-03-02	107	29			
1960467	Social	Kulan 6	Ross River	Bedroom	2017-11-15	2018-03-02	107	27			
7256878	Social	Kulan 8	Ross River	Bedroom	2017-11-15	2018-03-02	107	45			
7675408	Social	Kulan 8 second tester	Ross River	Bedroom	2017-11-15	2018-03-02	107	25	Second radon tester		
1161678	Social	Lot 200	Ross River	Hallway	2017-11-15	2018-03-02	107	36			
8875736	Staff	Lot 243	Ross River	Hallway	2017-11-15	2018-03-02	107	423			
6950562	Social	Lots 90-6 & 90-7	Ross River	Upstairs Hallway	2017-11-15	N/A	0	N/A	Reported by YHC as not sent	236588-0--11/29/2018--Rob--Hallway	
2426096	Social	Quartzite 2	Ross River	Bedroom	2017-11-15	2018-03-02	107	24			
7105844	Social	Quartzite 22A	Ross River	Hallway	2017-11-15	2018-03-02	107	35			
4779344	Staff	Territorial Rd 1	Ross River	Hallway	2017-11-15	2018-03-02	107	136			
7872179	Staff	Territorial Rd 3	Ross River	Hallway	2017-11-15	2018-03-02	107	100			
6403000	Staff	Territorial Rd 5	Ross River	Hallway	2017-11-15	2018-03-02	107	117			
3700416	Staff	Territorial Rd 7	Ross River	Hallway	2017-11-15	2018-03-02	107	42			
7601941	Staff	Territorial Rd 9	Ross River	Hallway	2017-11-15	2018-03-02	107	114			
9941584	Staff	Craft St 1	Teslin	Upstairs Hallway	2017-11-21	2018-02-28	99	80			
4304093	Social	Craft St 11-101	Teslin	Outside Bedroom Door	2017-11-21	2018-02-28	99	25			
6250625	Social	Craft St 11-102	Teslin	Outside Bedroom	2017-11-21	2018-02-28	99	18			
7669773	Social	Craft St 11-103	Teslin	Outside Bedroom	2017-11-21	2018-02-28	99	15			
9478991	Social	Craft St 11-104	Teslin	Outside Bedroom	2017-11-21	2018-02-28	99	51			
4304648	Social	Craft St 11-105	Teslin	Outside Bedroom	2017-11-21	2018-02-28	99	13			
1068980	Social	Craft St 11-106	Teslin	Outside Bedroom	2017-11-21	2018-02-28	99	16			
4300935	Social	Craft St 11-201	Teslin	Main Living Room	2017-11-21	2018-02-28	99	0	<15 Bq/m3		
4292637	Social	Craft St 11-202	Teslin	Bedroom	2017-11-21	2018-02-28	99	0	<15 Bq/m3		
4304960	Social	Craft St 11-202 second tester	Teslin	Bedroom	2017-11-21	2018-02-28	99	6	Second radon tester		
2280774	Staff	Craft St 2	Teslin	Hallway	2017-11-21	2018-02-28	99	74			
3539137	Staff	Craft St 8	Teslin	Hallway Upstairs	2017-11-21	2018-02-28	99	79			
4295374	Social	Jackson Ave 3 YHC Office	Teslin	Hallway	2017-11-21	2018-02-28	99	81			
4304374	Staff	Jackson Ave 9A	Teslin	Hallway	2017-11-21	2018-02-28	99	20			
4301974	Staff	Jackson Ave 9B	Teslin	Hallway	2017-11-21	2018-02-28	99	59			
7248222	Social	Johnston Ave 20	Teslin	Downstairs Hallway	2017-11-21	2018-02-28	99	59			
4304796	Social	Johnston Ave 4A	Teslin	Upstairs Hallway	2017-11-21	2018-02-28	99	65			
4301321	Social	Johnston Ave 4B	Teslin	Upstairs Hallway	2017-11-21	2018-02-28	99	21			
1631829	Social	Johnston Ave 4B	Teslin	Upstairs Hallway	2017-11-21	2018-02-28	99	8	<15 Bq/m3		
1577626	Social	Nisutlin Dr 38A	Teslin	Hallway	2017-11-21	2018-02-28	99	29			
4304101	Social	Nisutlin Dr 38A second tester	Teslin	Hallway	2017-11-21	2018-02-28	99	0	Second radon tester		
2192565	Social	Nisutlin Dr 38B	Teslin	Hallway	2017-11-21	2018-02-28	99	41			
7575350	Social	Nisutlin Dr 42	Teslin	Living Room	2017-11-21	2018-02-28	99	62			
5870514	Social	Nisutlin Dr 44	Teslin	Living Room	2017-11-21	2018-02-28	99	59			
4958971	Staff	Sawmill Rd 3	Teslin	Hallway	2017-11-21	2018-02-28	99	110			
1710086	Staff	Sidney St 1A	Teslin	Hallway	2017-11-21	2018-02-28	99	30			
4301594	Staff	Sidney St 1B	Teslin	Bedroom	2017-11-21	2018-02-28	99	77			
4306957	Staff	Sidney St 1B second tester	Teslin	Bedroom	2017-11-21	2018-02-28	99	10	Second radon tester		
7416670	Staff	Sidney St 1C	Teslin	Bedroom	2017-11-21	2018-02-28	99	40			
4270393	Staff	Sidney St 1D	Teslin	Bedroom	2017-11-21	2018-02-28	99	38			
2332971	Social	Smith St 6	Teslin	Hallway	2017-11-21	2018-02-28	99	73			
4303285	Social	Smith St 7	Teslin	Upstairs Hallway	2017-11-21	2018-02-28	99	41			
2594927	Staff	Smith St 9A	Teslin	Hallway	2017-11-21	2018-02-28	99	77			
4295754	Staff	Smith Street 9B	Teslin	Hallway	2017-11-21	2018-02-28	99	50			
3037637	staff	8th Ave 205A	Watson Lake	Hallway	2017-11-22	2018-03-02	100	92			
1966308	staff	8th Ave 205B	Watson Lake	Hallway	2017-11-22	2018-03-02	100	62			
3606989	staff	Campbell 101-1	Watson Lake	Hallway	2017-11-22	2018-03-02	100	209			
2025716	staff	Campbell 101-2	Watson Lake	Hallway	2017-11-22	2018-03-02	100	85			
2657039	staff	Campbell 101-2 second tester	Watson Lake	Hallway	2017-11-22	2018-03-02	100	90	Second radon tester		
3417201	staff	Campbell 101-3	Watson Lake	Hallway	2017-11-22	2018-03-02	100	177			
3961745	staff	Campbell 101-4	Watson Lake	Hallway	2017-11-22	2018-03-02	100	164			
4116083	Staff	Campbell 118A	Watson Lake	Hallway	2017-11-22	2018-03-02	100	20			
1334952	Staff	Campbell 118B	Watson Lake	Hallway	2017-11-22	2018-03-02	100	33			
6230841	Staff	Campbell 120A	Watson Lake	Hallway	2017-11-22	2018-03-02	100	161			
1021500	staff	Campbell 120B	Watson Lake	Hallway	2017-11-22	2018-03-02	100	44			
2530277	Staff	Campbell 125	Watson Lake	Bdrm Bm	2017-11-22	2018-03-02	100	331			
9967290	staff	Campbell 131	Watson Lake	Bdrm Bm	2017-11-22	2018-03-02	100	172			
2106607	staff	Campbell 131 second tester	Watson Lake	Bdrm Bm	2017-11-22	2018-03-02	100	171	Second radon tester		
4291639	staff	Finlayson 800-1	Watson Lake	Hallway	2017-11-22	2018-03-02	100	126			

7629413	staff	Finlayson 800-2	Watson Lake	Hallway	2017-11-22	2018-03-02	100	134			
4981544	staff	Finlayson 800-3	Watson Lake	Hallway	2017-11-22	2018-03-02	100	107			
1135615	staff	Finlayson 800-4	Watson Lake	Hallway	2017-11-22	2018-03-02	100	107			
1478239	staff	Finlayson 801A	Watson Lake	Hallway	2017-11-22	2018-03-02	100	84			
2370948	staff	Finlayson 801A second tester	Watson Lake	Hallway	2017-11-22	N/A	0		Second radon tester		
7969769	Staff	Finlayson 803A	Watson Lake	Hallway	2017-11-22	2018-03-02	100	39			
4298723	Senior	Finlayson Ave 806-101	Watson Lake	Hallway	2017-11-22	2018-03-02	100	37			
3756673	Senior	Finlayson Ave 806-102	Watson Lake	Hallway	2017-11-22	2018-03-02	100	57			
1581263	Senior	Finlayson Ave 806-102 second te	Watson Lake	Hallway	2017-11-22	2018-03-02	100	65	Second radon tester		
4304408	Senior	Finlayson Ave 806-103	Watson Lake	Hallway	2017-11-22	2018-03-02	100	35			
3672359	Senior	Finlayson Ave 806-104	Watson Lake	Hallway	2017-11-22	2018-03-02	100	33			
7449945	Senior	Finlayson Ave 806-105	Watson Lake	Hallway	2017-11-22	2018-03-02	100	23			
3601093	Senior	Finlayson Ave 806-106	Watson Lake	Hallway	2017-11-22	2018-03-02	100	43			
1170331	Staff	Hyland 702	Watson Lake	Basement Living Rm	2017-11-22	2018-03-02	100	160			
4305132	Staff	Hyland 702 second tester	Watson Lake	Basement Living Rm	2017-11-22	2018-03-02	100	190	Second radon tester		
4299756	Social	Liard 605A	Watson Lake	Upper Hallway	2017-11-22	2018-03-02	100	42			
1023845	Staff	Liard 611A	Watson Lake	Hallway	2017-11-22	2018-03-02	100	369			
6618516	Social	Liard 618	Watson Lake	Bdrn Hallway	2017-11-22	2018-03-02	100	32			
4299608	Social	Liard 700A	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	8	<15 Bq/m3		
1323757	Social	Liard 700A second tester	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	114	Second radon tester		
2026441	Social	Liard 700B	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	61			
4294138	Social	Liard 704A	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	50			
4296505	Social	Liard 704B	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	67			
7397987	Social	Liard 707A	Watson Lake	Living Rm	2017-11-22	2018-03-02	100	57			
3654027	Social	Liard 707B	Watson Lake	Living Rm	2017-11-22	2018-03-02	100	166			
2314375	Social	Liard 716A	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	278			
9928615	Social	Liard 716B	Watson Lake	Bottom Stairs	2017-11-22	2018-03-02	100	63			
9969023	Staff	Liard 719	Watson Lake	Hallway	2017-11-22	2018-03-02	100	283			
9765496	Social	Liard Ave 708	Watson Lake	Hallway	2017-11-22	2018-03-02	100	92			
1411453	Social	Morely 109B	Watson Lake	Hallway	2017-11-22	2018-03-02	100	124			
6003985	Social	Morely 111B	Watson Lake	Hallway	2017-11-22	2018-03-02	100	132			
1631308	Social	Morely 113	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	197			
1714617	Social	Morley 101	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	27			
2182202	Social	Morley 103	Watson Lake	Hallway	2017-11-22	2018-03-02	100	72			
3555497	Social	Nisutlin 1	Watson Lake	Hall	2017-11-22	2018-03-02	100	32			
9696972	Social	Nisutlin 101	Watson Lake	Basement Hall	2017-11-22	2018-03-02	100	413			
2559664	staff	Nisutlin 105	Watson Lake	Basement Bdrn	2017-11-22	2018-03-02	100	238			
4620282	staff	Nisutlin 106	Watson Lake	Base Bdrn	2017-11-22	2018-03-02	100	332			
9730151	Staff	Nisutlin 108	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	371			
7698556	Social	Nisutlin 113	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	137			
4246815	Social	Nisutlin 120	Watson Lake	Bdrn Bm	2017-11-22	N/A	0		N/A Reported by YHC as not sent		
7063985	Staff	Nisutlin 122	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	128			
4111209	Social	Nisutlin 123	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	114			
4302766	Social	Nisutlin 129	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	117			
1440346	Social	Nisutlin 129 second tester	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	161	Second radon tester		
7491319	Social	Nisutlin 2	Watson Lake	Hall	2017-11-22	2018-03-02	100	53			
3478104	Social	Nisutlin 3	Watson Lake	Hall	2017-11-22	2018-03-02	100	75			
6959969	Social	Nisutlin 4	Watson Lake	Hall	2017-11-22	2018-03-02	100	42			
2089241	Social	Nisutlin 4 second tester	Watson Lake	Hall	2017-11-22	2018-03-02	100	59	Second radon tester		
1051655	Social	Ravenhill 925	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	101			
1022318	Social	Ravenhill Dr 1008	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	218			
4292843	Social	Ravenhill Dr 1010	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	18			
4301313	Social	Ravenhill Dr 914	Watson Lake	Hallway	2017-11-22	2018-03-02	100	179			
3267937	Social	Ravenhill Dr 916B	Watson Lake	Hallway	2017-11-22	2018-03-02	100	135			
2392819	Staff	Ravenhill Dr 918	Watson Lake	Hallway	2017-11-23	2018-03-02	99	39			
4303491	Staff	Ravenhill Dr 920	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	47			
9167511	Staff	Ravenhill Dr 921	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	294			
1768597	Staff	Robert Campbell Hwy 204A	Watson Lake	Bdrn Bm	2017-11-23	2018-03-02	99	22			
2659555	Staff	Robert Campbell Hwy 204B	Watson Lake	Bdrn Bm	2017-11-23	2018-03-02	99	54			
7703184	Staff	Simpson Dr 201	Watson Lake	Bdrn Bm	2017-11-22	2018-03-02	100	203			
7679707	Staff	Simpson Dr 203	Watson Lake	Hallway	2017-11-22	2018-03-02	100	1121			Device 129617-7 [Bottom of Stairs] & 497951-4 [hallway] placed by Darren on 11/21/2018
4414025	Staff	Simpson Dr 205	Watson Lake	Hallway	2017-11-23	2018-03-02	99	297			
3171808	Staff	Watson Lake office space	Watson Lake	At Desk Wall	2017-11-23	2018-03-02	99	100			
3198199	Social	13th Ave 44	Whitehorse	Hallway	2017-11-16	2018-03-05	109	336			New ground sheet was installed Dec 2018. 344681-2--1/4/2019--Phil--Hallway
4296844	Senior	3rd Ave 3090-102	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	39			
7478258	Senior	3rd Ave 3090-103	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	24			
4305942	Senior	3rd Ave 3090-104	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	23			
4168936	Senior	3rd Ave 3090-105	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	14	<15 Bq/m3		
1736180	Senior	3rd Ave 3090-106	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	70			
1861681	Senior	3rd Ave 3090-106 second tester	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	65	Second radon tester		
7412448	Senior	3rd Ave 3090-107	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	13	<15 Bq/m3		
7053572	Senior	3rd Ave 3090-108	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	88			
4170619	Senior	3rd Ave 3090-109	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	32			
4295531	Senior	3rd Ave 3090-110	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	45			
1761873	Senior	3rd Ave 3090-111	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	51			
4294674	Senior	3rd Ave 3090-112	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	56			
4298444	Senior	3rd Ave 3090-113	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	6	<15 Bq/m3		
3376951	Social	4th Avenue 4050-101	Whitehorse	102 Hallway	2017-11-27	2018-03-08	101	126			
5899803	Social	6th Ave 6095-101	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	180			
4176392	Social	6th Ave 6095-102	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	58			
1107101	Social	6th Ave 6095-103	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	83			
4182432	Social	6th Ave 6095-104	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	132			
7322324	Social	6th Ave 6095-105	Whitehorse	Hallway	2017-11-20	2018-03-05	105	44			
4250494	Social	6th Ave 6095-106	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	97			
4214076	Social	6th Ave 6095-A	Whitehorse	Basement Bedroom	2017-11-20	2018-03-05	105	46			
2522324	Social	6th Ave 6095-B	Whitehorse	Basement Bedroom	2017-11-20	2018-03-05	105	64			
2012045	Social	6th Ave 6095-C	Whitehorse	Living Room	2017-11-20	2018-03-05	105	93			
1129204	Social	6th Ave 6095-C second tester	Whitehorse	Living Room	2017-11-20	2018-03-05	105	77	Second radon tester		
7538077	Social	6th Ave 6095-D	Whitehorse	Basement Bedroom	2017-11-20	2018-03-05	105	73			

2663367	Social	6th Ave 6123-101	Whitehorse	Living Room	2017-11-21	2018-03-08	107	32			
4227641	Social	6th Ave 6123-102	Whitehorse	Living Room	2017-11-21	2018-03-08	107	21			
2178176	Social	6th Ave 6123-102 second tester	Whitehorse	Living Room	2017-11-21	2018-03-08	107	26	Second radon tester		
1146570	Social	6th Ave 6123-103	Whitehorse	Bedroom	2017-11-21	2018-03-08	107	20			
1102664	Social	6th Ave 6123-104	Whitehorse	Living Room	2017-11-21	2018-03-08	107	17			
4212098	Social	6th Ave 6123-105	Whitehorse	Living Room	2017-11-21	2018-03-08	107	23			
5572599	Social	6th Ave 6123-106	Whitehorse	Bedroom	2017-11-21	2018-03-08	107	29			
2023307	Social	9th Ave 23	Whitehorse	Hallway	2017-11-16	2018-03-05	109	50			
6658728	Senior	Alexander St 207-101	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	15			
4291985	Senior	Alexander St 207-102	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	46			
6816367	Senior	Alexander St 207-103	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	33			
4292397	Senior	Alexander St 207-104	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	30			
1945187	Senior	Alexander St 207-105	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	45			
4301586	Senior	Alexander St 207-105	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	37			
1492362	Senior	Alexander St 207-107	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	27			
4265856	Senior	Alexander St 207-108	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	33			
1730340	Social	Alexander St 408-101	Whitehorse	Hallway above T-Stat	2017-11-21	2018-03-05	104	48			
6555858	Social	Alexander St 408-102	Whitehorse	Above T-Stat Living Room	2017-11-21	2018-03-05	104	117			
4163481	Social	Alexander St 408-103	Whitehorse	Above T-Stat Living Room	2017-11-21	2018-03-05	104	50			
5931043	Social	Alexander St 408-103 second tes	Whitehorse	Above T-Stat	2017-11-21	2018-03-05	104	60	Second radon tester		
4230405	Social	Alexander St 408-104	Whitehorse	Near Bed	2017-11-21	2018-03-05	104	58			
4231494	Social	Alexander St 408-105	Whitehorse	Living Room	2017-11-21	2018-03-05	104	204			
4176707	Social	Alexander St 408-106	Whitehorse	Living Room	2017-11-21	2018-03-05	104	174			
5588520	Social	Bamboo Cr 26A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	35			
4386363	Social	Bamboo Cr 26B	Whitehorse	Bsmt Hallway	2017-11-16	2018-03-05	109	23			
1225606	Social	Bamboo Cr 28A	Whitehorse	Bsmt Hallway	2017-11-16	2018-03-05	109	22			
3644663	Social	Bamboo Cr 28B	Whitehorse	Main Floor	2017-11-16	2018-03-05	109	17			
1039577	Social	Centennial St 2004-1A	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	524			New ground sheet was installed Nov 2018. 778793-0-12/5/2018--Phil--Hallway
4290417	Social	Centennial St 2004-1B	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	158			
6877757	Social	Centennial St 2004-2A	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	165			
2379683	Social	Centennial St 2004-2B	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	203			
4186882	Social	Centennial St 2004-3A	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	130			
4289963	Social	Centennial St 2004-3B	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	62			
7509086	Social	Centennial St 2004-4A	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	72			
2598159	Social	Centennial St 2004-4B	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	125			
6619480	Social	Centennial St 2004-5A	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	63			
3287950	Social	Centennial St 2004-5B	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	144			
5027966	Social	Centennial St 2004-6A	Whitehorse	Hallway Main Floor	2017-11-16	2018-03-05	109	55			
2019636	Social	Centennial St 2101-101A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	16			
4298527	Social	Centennial St 2101-101B	Whitehorse	Hallway	2017-11-16	2018-03-05	109	25			
4298555	Social	Centennial St 2101-102A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	121			
7920986	Social	Centennial St 2101-102B	Whitehorse	Hallway	2017-11-16	2018-03-05	109	114			
1389543	Social	Centennial St 2101-103A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	157			
3604121	Social	Centennial St 2101-103B	Whitehorse	Hallway	2017-11-16	2018-03-05	109	67			
1215946	Social	Centennial St 2101-104A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	203			
4285144	Social	Centennial St 2101-104B	Whitehorse	Hallway	2017-11-16	2018-03-05	109	102			
7722796	Social	Centennial St 2101-105A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	113			
1623487	Social	Centennial St 2101-105A second	Whitehorse	Hallway	2017-11-16	2018-03-05	109	97	Second radon tester		
4289716	Social	Centennial St 2101-105B	Whitehorse	Hallway	2017-11-16	2018-03-05	109	110			
4303137	Social	Centennial St 2101-106A	Whitehorse	Hallway	2017-11-16	2018-03-05	109	133			
7298037	Social	Centennial St 2101-106B	Whitehorse	Hallway	2017-11-16	2018-03-05	109	271			
6264725	Senior	College Dr 600-101	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	36			
4301636	Senior	College Dr 600-102	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	52			
1319896	Senior	College Dr 600-103	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	44			
4306023	Senior	College Dr 600-104	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	19			
1330588	Senior	College Dr 600-105	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	26			
3600152	Senior	College Dr 600-106	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	28			
1480003	Senior	College Dr 600-107	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	30			
4304036	Senior	College Dr 600-108	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	38			
4377709	Senior	College Dr 600-109	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	23			
6560031	Senior	College Dr 600-109 second teste	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	39	Second radon tester		
4294278	Senior	College Dr 600-110	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	60			
2192086	Senior	College Dr 600-111	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	38			
3383437	Senior	College Dr 600-112	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	36			
1960640	Senior	College Dr 600-113	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	31			
2606929	Senior	College Dr 600-114	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	44			
7586860	Senior	College Dr 600-115	Whitehorse	Bedroom	2017-11-14	2018-03-05	111				
3554045	Senior	College Dr 600-116	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	36			
4444790	Senior	College Dr 600-316	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	34			
4162889	Senior	College Dr 600-bsmt common ar	Whitehorse	Wall New Piano	2017-11-14	2018-03-05	111	373			
3120110	Senior	College Dr 600-bsmt rm 15	Whitehorse	Rm 15 Wall	2017-11-14	2018-03-05	111	861			
4203444	Social	Cook St 702A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-03-01	101				
4169859	Social	Cook St 702B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-03-01	101	58			
6629224	Social	Doniek Rd 27	Whitehorse	Hallway	2017-11-14	2018-03-08	114	88			
5071261	Social	Drury St 506A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-03-01	101	94			
5823935	Social	Drury St 506B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-03-01	101	82			
4302352	Social	Firth Rd 20	Whitehorse	Hallway	2017-11-09	2018-03-08	119	262			
5727755	Senior	Front St 1190-101	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	10	<15 Bq/m3		
4301818	Senior	Front St 1190-102	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	21			
4305678	Senior	Front St 1190-103	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	4	<15 Bq/m3		
7622657	Senior	Front St 1190-104	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	10	<15 Bq/m3		
7945629	Senior	Front St 1190-105	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	48			
4298600	Senior	Front St 1190-106	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	24			
1737493	Senior	Front St 1190-107	Whitehorse	Bedroom	2017-11-14	2018-03-05	111				
4298212	Senior	Front St 1190-108	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	0	<15 Bq/m3		
3580958	Senior	Front St 1190-109	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	52			
1537273	Senior	Front St 1190-110	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	40			
6873368	Social	Green Cr 5	Whitehorse	Hallway	2017-11-09	2018-03-08	119	157			
3500683	Social	Green Cr 7	Whitehorse	Hallway	2017-11-09	2018-03-08	119	30			
3383247	Senior	Hanson St 301A	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	48			

4169611	Senior	Hanson St 301B	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	44			
2108389	Senior	Hanson St 303A	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	38			
4225223	Senior	Hanson St 303B	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	63			
1112150	Senior	Hanson St 307A	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	69			
9672304	Senior	Hanson St 307B	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	42			
2328763	Senior	Hanson St 309A	Whitehorse	Living Room/Hallway	2017-11-20	2018-03-05	105	38			
7469828	Senior	Hanson St 309B	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	39			
6098404	Senior	Hanson St 311A	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	39			
9922030	Senior	Hanson St 311B	Whitehorse	Bedroom	2017-11-20	2018-03-05	105	50			
7907894	Social	Hart Cr 37	Whitehorse	Hallway Bsmr	2017-11-09	2018-03-08	119	211			
2089829	Social	Jeckell St 403A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	24			
6339691	Social	Jeckell St 403B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	35			
7922693	Social	Jeckell St 403C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	118			
6090450	Social	Jeckell St 405A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	45			
5069729	Social	Jeckell St 405B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	14	<15 Bq/m3		
2042919	Social	Jeckell St 405B second tester	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	20	Second radon tester		
5068432	Social	Jeckell St 405C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	19			
9895517	Social	Jeckell St 408A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	32			
4901587	Social	Jeckell St 408B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	27			
4177374	Social	Jeckell St 506A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	42			
1888973	Social	Jeckell St 506B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	46			
6828727	Social	Jeckell St 506C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99				412941-7--11/26/2018--Phil--Hallway
1672500	Social	Jeckell St 507A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	30			
6174502	Social	Jeckell St 507B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	56			
7020134	Social	Jeckell St 507C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	24			
1129089	Social	Jeckell St 508A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	29			
7730195	Social	Jeckell St 508B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	44			
4120283	Social	Jeckell St 509A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	15			
7944465	Social	Jeckell St 509B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-27	99	39			
1108422	Social	Ketza Rd 13B	Whitehorse	Hallway	2017-11-09	2018-03-08	119	572	mitigated by Erik S summer 2018. Sealed obvious spots,	44	724213-4--11/30/2018--Phil--Hallway
2191284	Senior	Lambert St 100-101	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	12	<15 Bq/m3		
8617492	Senior	Lambert St 100-102	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	21			
2563526	Senior	Lambert St 100-103	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	13	<15 Bq/m3		
1005230	Senior	Lambert St 100-103 second tester	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	15	Second radon tester		
4304952	Senior	Lambert St 100-104	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	23			
4304150	Senior	Lambert St 100-105	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	22			
4299210	Senior	Lambert St 100-107	Whitehorse	Bedroom	2017-11-09	2018-03-05	116	19			
3466042	Social	Lambert St 100A Commissioners	Whitehorse	Wall	2017-11-28	2018-03-05	97	28			
7677842	Social	Lambert St 100B Film/Sound	Whitehorse	Wall	2017-11-28	2018-03-08	100	41			
1188283	Social	Lambert St 501A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	141			
5850425	Social	Lambert St 501B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	155			
4282380	Social	Lambert St 503A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	77			
3904190	Social	Lambert St 503B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	134			
3210051	Social	Lewes Blvd 35-19	Whitehorse	Bedroom	2017-11-09	2018-03-08	119	41			
7038094	Social	Lewes Blvd 35-17	Whitehorse	Bedroom	2017-11-09	2018-03-08	119	27			
4306538	Social	Lewes Blvd 35-18	Whitehorse	Bedroom	2017-11-09	2018-03-08	119	29			
5535679	Social	Lewes Blvd 35-3	Whitehorse	Hallway	2017-11-09	2018-03-08	119	15			
2563419	Social	Lewes Blvd 35-6	Whitehorse	Bedroom	2017-11-09	2018-03-08	119	25			
6834147	Social	Liard Rd 5	Whitehorse	Hallway	2017-11-09	2018-03-08	119	38			
6655278	Social	Lowe Street 410	Whitehorse	Basement Hallway	2017-11-27	2018-03-07	100	101			
1439751	Social	Mallard Way 85	Whitehorse	Main Floor Bedroom	2017-11-21	2018-03-05	104	121			
4300778	Social	Mallard Way 87	Whitehorse	Living Room	2017-11-21	2018-03-05	104	32			
4296240	Social	Mallard Way 89	Whitehorse	Dining Room	2017-11-21	2018-03-05	104	125			
4293973	Social	Mallard Way 91	Whitehorse	Living Room	2017-11-21	2018-03-05	104	62			
4165262	Social	Mallard Way 93	Whitehorse	Dining Room	2017-11-21	2018-03-05	104	93			
1039858	Social	Mallard Way 95	Whitehorse	Living Room	2017-11-21	2018-03-05	104	115			
1677061	Social	Pelly Rd 32	Whitehorse	Bsmr Bedroom	2017-11-09	2018-03-08	119	64			
4300943	Social	Redwood St 8	Whitehorse	Hallway lower floor	2017-11-16	2018-03-05	109	23			
4331542	Social	Rhine Way 31	Whitehorse	Living Room	2017-11-20	2018-03-08	108	117			
4228599	Social	Rhine Way 33	Whitehorse	Living Room	2017-11-20	2018-03-05	105	41			
2422897	Social	Rhine Way 35	Whitehorse	Living Room	2017-11-20	2018-03-05	105	35			
2241362	Social	Rhine Way 35 second tester	Whitehorse	Living Room	2017-11-20	2018-03-05	105	43	Second radon tester		
5050067	Social	Rhine Way 37	Whitehorse	Living Room	2017-11-20	2018-03-08	108	111			
1619162	Social	Rhine Way 39	Whitehorse	Living Room	2017-11-20	2018-03-08	108	76			
1299411	Social	Rhine Way 41	Whitehorse	Living Room	2017-11-20	2018-03-05	105	67			
4163549	Social	Selkirk St 60-111	Whitehorse	Wall Dining	2017-11-09	2018-03-07	118	31			
4296315	Social	Selkirk St 60-112	Whitehorse	Wall Dining	2017-11-09	2018-03-07	118	5			
4300844	Social	Selkirk St 60-113	Whitehorse	Wall Dining	2017-11-09	2018-03-07	118	10	<15 Bq/m3		
6813232	Social	Selkirk St 60-114	Whitehorse	Wall Dining	2017-11-09	2018-03-07	118	44			
1028042	Social	Selkirk St 60-211	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	28			
4219598	Social	Selkirk St 60-212	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	21			
4292728	Social	Selkirk St 60-213	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	15			
9910720	Social	Selkirk St 60-214	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	24			
4303046	Social	Selkirk St 60-311	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	34			
7911605	Social	Selkirk St 60-312	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	33			
4215612	Social	Selkirk St 60-313	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	37			
2559037	Social	Selkirk St 60-314	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	32			
7221278	Social	Selkirk St 60-411	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	18			
3650249	Social	Selkirk St 60-412	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	32			
9672114	Social	Selkirk St 60-413	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	37			
4292850	Social	Selkirk St 60-414	Whitehorse	Wall Dining	2017-11-09	2018-03-08	119	54			
4267084	Social	Tagish Rd 10	Whitehorse	Bedroom	2017-11-09	2018-03-08	119	48			
1598366	Social	Takhini Ave 4	Whitehorse	Bedroom	2017-11-09	2018-03-08	119	167			
4294633	Social	Tay St 27	Whitehorse	Bsmr Bedroom	2017-11-09	2018-03-08	119	75			
4227062	Social	Taylor St 502A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	66			
2313575	Social	Taylor St 502B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	27			
4954384	Social	Taylor St 504A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	36			
3402898	Social	Taylor St 504B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	46			
2674919	Social	Taylor St 504C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75				191064-5--11/26/2018--Phil--Hallway
7207822	Social	Taylor St 506A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75				209923-2--11/26/2018--Phil--Hallway

117765	Social	Taylor St 506B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	53			
1351303	Social	Taylor St 507A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	81			
1116623	Social	Taylor St 507B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	39			
6558324	Social	Taylor St 507C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	54			
1128123	Social	Taylor St 508A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75				162598-7--11/26/2018--Phil--Hallway
4210571	Social	Taylor St 508B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	40			
2657576	Social	Taylor St 508C	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	36			
1297621	Social	Taylor St 509A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	40			
3351590	Social	Taylor St 509B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	96			
2521540	Social	Taylor St 510A	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	23			
1330844	Social	Taylor St 510B	Whitehorse	Hallway above T-Stat	2017-11-20	2018-02-03	75	48			
4183778	Social	Thompson Rd 2-1	Whitehorse	Hallway Main Floor	2017-11-21	2018-03-05	104	17			
3607249	Social	Thompson Rd 2-10	Whitehorse		2017-11-21	2018-03-05	104	9	<15 Bq/m3		
4143749	Social	Thompson Rd 2-11	Whitehorse	Downstairs Hall	2017-11-21	2018-03-05	104	65			
4298584	Social	Thompson Rd 2-12	Whitehorse	Hallway Main Floor	2017-11-21	2018-03-05	104	36			
1115898	Social	Thompson Rd 2-13	Whitehorse	Downstairs Bedroom	2017-11-21	2018-03-05	104	38			
7058464	Social	Thompson Rd 2-14	Whitehorse	Basement Hallway	2017-11-21	2018-03-05	104	57			
7598402	Social	Thompson Rd 2-2	Whitehorse	Hallway Main Floor	2017-11-21	2018-03-05	104	10	<15 Bq/m3		
1958685	Social	Thompson Rd 2-2 second tester	Whitehorse	Hallway Main Floor	2017-11-21	2018-03-05	104	15	Second radon tester		
4232617	Social	Thompson Rd 2-3	Whitehorse	Hallway Main Floor	2017-11-21	2018-03-05	104	32			
4293783	Social	Thompson Rd 2-4	Whitehorse	Hallway Main Floor	2017-11-21	2018-03-05	104	11	<15 Bq/m3		
2760247	Social	Thompson Rd 2-5	Whitehorse	Upstairs Living Room	2017-11-21	2018-03-05	104	79			
7559073	Social	Thompson Rd 2-6	Whitehorse	Living Room Wall	2017-11-21	2018-03-05	104	32			
4213476	Social	Thompson Rd 2-7	Whitehorse	Living Room	2017-11-21	2018-03-05	104	36			
4183307	Social	Thompson Rd 2-8	Whitehorse	Hallway Wall	2017-11-21	2018-03-05	104	1	<15 Bq/m3		
4300190	Social	Thompson Rd 2-9	Whitehorse	Hall	2017-11-21	2018-03-05	104	26			
6815989	Social	Thompson Rd 6-101	Whitehorse	Hallway	2017-11-21	2018-03-05	104	16			
4164091	Social	Thompson Rd 6-101 second test	Whitehorse	Hallway	2017-11-21	2018-03-05	104	16	Second radon tester		
4214714	Social	Thompson Rd 6-102	Whitehorse	Living Room	2017-11-21	2018-03-05	104	12	<15 Bq/m3		
4162806	Social	Thompson Rd 6-103	Whitehorse	Hallway	2017-11-21	2018-03-05	104	17			
4224986	Social	Thompson Rd 6-104	Whitehorse	Living Room	2017-11-21	2018-03-05	104	10	<15 Bq/m3		
4301651	Social	Thompson Rd 6-105	Whitehorse	Hallway	2017-11-21	2018-03-05	104	0	<15 Bq/m3		
6583108	Social	Thompson Rd 6-106	Whitehorse	Living Room	2017-11-21	2018-03-05	104	16			
7627706	Social	Thompson Rd 6-107	Whitehorse	Hallway	2017-11-21	2018-03-05	104	25			
1317023	Social	Thompson Rd 6-108	Whitehorse	Living Room	2017-11-21	2018-03-05	104	19			
2956886	Social	Wann Rd 33	Whitehorse	Hallway	2017-11-16	2018-03-05	109	203			
9939224	Senior	Waterfront Pl 22-111	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	35			
9536269	Senior	Waterfront Pl 22-112	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	39			
1139096	Senior	Waterfront Pl 22-113	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	22			
7302565	Senior	Waterfront Pl 22-114	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	22			
4295135	Senior	Waterfront Pl 22-115	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	35			
4303897	Senior	Waterfront Pl 22-116	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	23			
3438173	Senior	Waterfront Pl 22-117	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	12	<15 Bq/m3		
4293296	Senior	Waterfront Pl 22-118	Whitehorse	Bedroom	2017-11-14	2018-03-05	111	9	<15 Bq/m3		
2345106	Senior	Waterfront Pl 22-119	Whitehorse	Living Room	2017-11-14	2018-03-05	111				
2592483	Social	Wheeler St A	Whitehorse	Bedroom	2017-11-21	2018-03-05	104	50			
9706318	Social	Wheeler St B	Whitehorse	Living Room/Kitchen	2017-11-21	2018-03-05	104	113			
7754252	Social	Wheeler St C	Whitehorse	Living Room	2017-11-21	2018-03-05	104	202			
1121243	Social	Wheeler St D	Whitehorse	Bedroom	2017-11-21	2018-03-05	104	179			
1264571	Social	Wheeler St D second tester	Whitehorse	Bedroom	2017-11-21	2018-03-05	104	184	Second radon tester		

	Unit Number	Notes	City	Radon level (Bq/m3)	Recorded Radon level (Bq/m3) post mitigation	Radon vent installed	serial no	date	location
203 Simpson Dr	8857	Mitigated in May 2019 by All Pro Yukon	Watson Lake	1121	119	Yes	323859-9		
600 College drive lower (one storage room)		Fans installed by Cory Sands Jan 2019	Whitehorse	861		Yes			
Lot 10	8678	Mitigated in September 2018 by E.S. 2 x Electro	Pelly Crossing	761	44	Yes	592537-5		1/14/2022
10 Center Street #1	4110	Mitigated in January 2019 by E.S.	Mayo	575	28	Yes	907360-2		12/14/2021
13 B Ketza Road	0802	Mitigated in August 2018 by E.S. Long term tes	Whitehorse	572	30	Yes	218648-4		12/16/2021
1A -2004 Centennial Str	0840	New ground sheet installed. Long term tester in	Whitehorse	524	131	No	905222-6		12/16/2021
25 Laurier Str	8656	partially finished basement	Mayo	491	57	Yes	704185-8		12/14/2021
Lot 90-6/90-7	8790	Mitigated by Cory Sands July 2019	Ross River	426	80	Yes	910649-3		1/4/2022
Lot 243	8745	Mitigated by Cory Sands July 2019	Ross River	423	44	Yes	327815-7		1/4/2022
101 Nisutlin	7151	Mitigated in May 2019 by All Pro Yukon	Watson Lake	413	86	Yes	942318-7		
600 College drive lower floor common area		Fans installed by Cory Sands Jan 2019	Whitehorse	373		Yes			
108 Nisutlin	8849	Mitigated in May 2019 by All Pro Yukon	Watson Lake	371		Yes	954161-6		
A-611 Liard	8862	Mitigated in May 2019 by All Pro Yukon	Watson Lake	369	183	Yes	283937-1		
44-13th Avenue	6336	New ground sheet installed. Long term tester in	Whitehorse	336	209	No	135443-0		12/16/2021
106 Nisutlin	8513	Mitigated in May 2019 by All Pro Yukon	Watson Lake	332	27	Yes	605139-5		
125 Campbell	8511	Mitigated in May 2019 by All Pro Yukon	Watson Lake	331	173	Yes	753612-1		
310 5th Ave	8907	Mitigated in May 2019 by All Pro Yukon	Mayo	310	32	Yes	475567-4		12/14/2021
4th St W Lot 179	2621	Mitigated by Cory Sands July 2019	Ross River	299	120	Yes	177660-8		1/4/2022
205 Simpson Dr	8859	Mitigated in May 2019 by All Pro Yukon	Watson Lake	297	24	Yes	187970-9		
921 Ravenhill	8843	Mitigated in May 2019 by All Pro Yukon	Watson Lake	294	26	Yes	439736-0		
719 Liard	8818	Mitigated in May 2019 by All Pro Yukon	Watson Lake	283	112	Yes	660172-8		
A-716 Liard	1301	Mitigated in May 2019 by All Pro Yukon	Watson Lake	278	34	Yes	950481-2		
1-356 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	second tester 272	46	Yes	971922-0		
106B-2101 Centennial Str	0837	Spray foam done to crawl space	Whitehorse	271	140	No	408198-0		12/16/2021
20 Firth Road	0804	mitigated	Whitehorse	262	73	Yes	484197-9		12/16/2021
149 River Rd	8312	mitigated by Cory Sands Oct 2019	Carmacks	247	45	Yes	282122-1		
105 Nisutlin	8512	Mitigated in May 2019 by All Pro Yukon	Watson Lake	238	55	Yes	984061-2		
4-362 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	233	43	Yes	668899-8		
21B Laurier	1207	Mitigated in May 2019 by All Pro Yukon	Mayo	233	66	Yes	270365-0		12/14/2021
Lot 1001 Quad 115115	8677	Mitigated in May 2019 by All Pro Yukon	Pelly Crossing	230	43	Yes	489943-1		1/14/2022
5-364 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	226	47	Yes	757647-3		
2-358 Campbell St	8706	Mitigated by Cory Sands July 2019	Faro	223	41	Yes	217494-4		
1008 Ravenhill Dr	7154	Mitigated in May 2019 by All Pro Yukon	Watson Lake	218	51	Yes	975435-9		
18A Laurier	1205	Mitigated in May 2019 by All Pro Yukon	Mayo	217	30	Yes	279174-7		12/14/2021
101 Rose Cr unit 4	4900	Mitigated by Cory Sands July 2019	Faro	216	28	Yes	542747-1		
311 6th Ave	1201	Mitigated in May 2019 by All Pro Yukon	Mayo	216	29	Yes	984157-8		12/14/2021
37 Hart Crescent	0803	mitigated	Whitehorse	211	19	Yes	653092-7		12/16/2021
1-101 Campbell	8915	Mitigated in May 2019 by All Pro Yukon	Watson Lake	209	61	Yes	596179-2		
131 Alsek	2329	Mitigated in Nov 2019 All Pro Yukon	Haines Junction	204	156	Yes	114936-8		
105 - 408 Alexander Street	3001	finished basment	Whitehorse	204		No	590485-9		
201 Simpson Dr	8855	Mitigated in May 2019 by All Pro Yukon	Watson Lake	203	25	Yes	722453-8		
104A-2101 Centennial Str	0837	Spray Foam done to crawl space	Whitehorse	203	41	No	656946-1		12/16/2021
2B -2004 Centennial Str	0840	mitigated	Whitehorse	203	50	Yes	691549-0		12/16/2021
33 Wann Road	6342	mitigated	Whitehorse	203	108	Yes	444015-2	not done	
C-Wheeler	3004	vent is working -- new fan installed Jan 2019/e	Whitehorse	202	20	Yes	215696-6		12/16/2021
162 Alsek	8445	Mitigated in Nov 2019 All Pro Yukon	Haines Junction	198	61	Yes	683663-9		

Health Canada recommends
reducing radon levels below
200 Bq/m3, within 1 year if the
radon test indicates levels
above 600 Bq/ m3; within 2 years
if the concentrations are
between 200 and 600 Bq/m3